

Site: FITOUT PROJECT AL-RAED RIYADH

WIR -Area-
Bldg site -
Disc

REQUEST No.

043

Rev.# Of Copies

1

To: CONSULTANT

Date:

25/12/2022

Serial

BBC-ECE-AR-WIR-03-R01

WORK INSPECTION REQUEST

We hereby request the Engineer's attendance to inspect the following work:

Level of Inspection: ☐ Hold ☐ Witness ☐ Release Inspection ☒ Handing

Location of Inspection: 5th Floor

Reference Documents and Attachments:

Specification #: ☐ MIR #: ☐ Inspection Checklist #: ☐ Certificate: ☐
Clearance & Releases: ☐ Marked-up Approved Shop Drawings: ☒ no sd attached.
Activity ID/BOQ: ☐ Date & Time of Inspection: ☐

Previous Inspection History:

Meeting Notes #: ☐ Testing Results: ☐ Issued NCR #: ☐

Description of Work: The six rows of basement masonry 1 archive room

Contractor's QC Report: works conforms to specifications

We certify that the submitted work for inspection has been executed in accordance with the contract's specification and approved shop drawing

PM. Name: Eng. tarek Reafaei

Signature: ☐

Date: 25/12/2022

QC Eng. Name: saleh alzubairi

Signature: ☐

Date: 25/12/2022

DC. Name: Ahmed Gamal

Signature: ☐

Date: 25/12/2022

Engineer's Inspection Comment:

* COMPLY WITH WORK STANDARD SPEC & AS PER INSTRUCTION
* NOT FOUND any surveyor marking point.
* He approved S.D approval given on behalf of contractor
* Repetition & Manager instruction

Inspection Status:

A - Approved / Proceed ☐

B - Approved with comments ☒

C - Rejected ☐

Name: Amrikham

Signature: ☐

Date: 26/12/22

Contractor's Received:

Received by:

Signature:

Acceptance of the request does not relieve the contractor from full compliance with the requirements of the contract's documents, dimensions selecting fabrication processes and techniques of construction, coordinating his work with that of other trades, and performing his work in a safe & satisfactory manner and correlating all quantities and conformance with the design concept of the project and general compliance with the information given in the contract documents

All requests must be submitted at least 24 hours prior to the required inspection and approval.

CC: ☐ AM ☐ QA/QC ☐

Area:

Site:

Discipline:

25.12.22
3:40

* Should clean entire area.
* After surveyor marking point should install vertical Rebar as per instruction

Should provide detail description with area name & a number & work activity.

26/12/2022